



SKU # RS-D1(P)

Part # 1004319

Description

D1(P) 12V 35W Factory OEM Ballast Input 9-16V Max Input Current 6.5A-88A fits most 2005-2012 Montego/Rover/Martin/Passat/Lacrosse



Categories HID & LED Headlights, HID Headlight Conversions

Sub-Categories HID Ballast and Bulb Parts, OEM Replacement Ballasts

UPC 814843025621

Unit of Measure EA

Related Skus:

Cross Sell Skus:

Condition

New

Manufacturer

Race Sport Lighting

EZ Category

OEM Replacement Ballasts

Harmonization Code

8512.20.2080

Universal

No

Life Expectancy

SEMA Product

High Intensity Discharge Lighting Ballast

Part Type ID 15962

Reverse Polarity

High Intensity Discharge Lighting Ballast

Operating Voltage

Current Draw

Wattage

35-Watts

Chip Type

N/A

IP Rating

IP67

LUX

N/A

Product Information

Whether you are looking to replace a failing OEM ballast or just looking to upgrade to a more reliable setup, Race Sport Lighting has you covered with vehicle specific OEM direct replacement ballasts. This High Intensity Discharge (HID) Control Module controls the current needed to ignite high intensity discharge headlight bulbs by increasing the voltage. Plug-and-play, direct-fit replacement ensures easy installation. These ballasts meet all factory specifications and requirements. Fits the following vehicles 2005-2007 Mercury Montego PN# 5T5Z13C170A 2008-2012 Land Rover LR2 PN# 021905 2006-2010 Aston Martin DB9 and DBS PN# 4G4313C169-AA 2009-2011 Aston Martin Vantage V8 PN# 4G4313C169-AA (DENZO HEDLIGHT ONLY) 2009-2010 Volkswagen Passat CC PN# 1K0941329 2010-2012 Buick Lacrosse PN # 22743220

Est. Labor

Hours

Gross Weight

0.40

Width

4.75

Net Weight

0.40

Height

2.00

DIM Weight

0.43

Depth

6.25

Kelvin (ColorTemperature)

N/A

Universal or Vehicle Specific

Vehicle Specific

Made In

CN

Warranty

1 year

Lumens

N/A

Beam Pattern

N/A

Prop 65 WARNING: This product can expose you to chemicals, which are known to the State of California to cause cancer and birth defects or other reproductive harm. For more information go to www.P65Warnings.ca.gov

www.racesportinc.com