



SKU # RS-D2(DY)

Part # 1004328

Description

Discontinued - D1(DY) 12V 35W Factory OEM Ballast Input 9-16V Max Input Current 6.5A-88A (2011-2014 Toyota Land Cruiser 2013-2014 Toyota Venza 2011-2014 Toyota Avalon 2012-2014 Toyota Sienna 2012-2014 Lexus GS 350, 300, 450h, 460 2013-2014 Lexus RX 350, 450h 2012-2014 Lexus LX 570 Toyota Rav4)

Categories HID & LED Headlights, HID Headlight Conversions

Sub-Categories HID Ballast and Bulb Parts, OEM Replacement Ballasts

UPC 814843025713

Unit of Measure EA

Related Skus:

Cross Sell Skus:

Condition
New

Manufacturer
Race Sport Lighting

EZ Category
OEM Replacement Ballasts

Harmonization Code
8512.20.2080

Universal
No

Life Expectancy

SEMA Product
High Intensity Discharge Lighting Ballast

Part Type ID 15962

Reverse Polarity
High Intensity Discharge Lighting Ballast

Operating Voltage

Current Draw

Wattage
35-Watts

Chip Type
N/A

IP Rating
IP67

LUX
N/A

Kelvin (ColorTemperature)
N/A

Universal or Vehicle Specific
Vehicle Specific

Made In
CN

Warranty
1 year

Lumens
N/A

Beam Pattern
N/A



Product Information

Whether you are looking to replace a failing OEM ballast or just looking to upgrade to a more reliable setup, Race Sport Lighting has you covered with vehicle specific OEM direct replacement ballasts. These ballasts are sold individually (Race Sport recommends replacing both ballasts) These ballasts meet all factory specifications and requirements. • 1 Year Warranty Fits the following vehicles 2011-2014 Toyota Land Cruiser 2013-2014 Toyota Venza 2011-2014 Toyota Avalon 2012-2014 Toyota Sienna 2012-2014 Lexus GS 350, 300, 450h, 460 2013-2014 Lexus RX 350, 450h 2012-2014 Lexus LX 570 2012-2014 Toyota Rav4 OEM Part Numbers: PN# 81107-60F10, PN# 81107-75020, PN# 85967-08020

Est. Labor	Hours		
Gross Weight	0.40	Width	4.75
Net Weight	0.40	Height	2.00
DIM Weight	0.43	Depth	6.25

Prop 65 WARNING: This product can expose you to chemicals, which are known to the State of California to cause cancer and birth defects or other reproductive harm. For more information go to www.P65Warnings.ca.gov