




SKU # RS-D1(M3)

Part # 1004314

Description

D1 (M3) 12V 35W Factory OEM Ballast Input 9-16V Direct fits 2006-2008 BMW and 2007+ Volvo



Categories HID & LED Headlights, HID Headlight Conversions

Sub-Categories HID Ballast and Bulb Parts, OEM Replacement Ballasts

UPC 814843025805 Unit of Measure EA

Related Skus:

Cross Sell Skus:

Condition New Manufacturer Race Sport Lighting EZ Category OEM Replacement Ballasts

Harmonization Code 8512.20.2080 Universal No Life Expectancy

SEMA Product High Intensity Discharge Lighting Ballast Part Type ID 15962

Reverse Polarity High Intensity Discharge Lighting Ballast Operating Voltage Current Draw

Wattage 35-Watts Chip Type N/A IP Rating IP67 LUX N/A

Product Information

Race Sport Lighting has you covered with vehicle specific direct replacement OEM ballasts. Is your car’s OEM Xenon Headlights having problems like Flickering, failure to power on, or just interment? Check the bulbs as they are usually the first to go however normally speaking, when it is not a bulb, 90% of the time it is just the ballast. No need to go to the car dealers to waste a lot of money to buy the whole headlight assembly. • These ballast are Sold individually (we recommend replacing both at the same time) • These ballast meet all factory specifications and requirements • 1 Year Warranty Fits the following vehicles 2006-2008 BMW 3-series (E90 / E91) Key: BMW 323i 2006-2008 BMW 325i 2004-2006 BMW 325Xi 2004-2006 BMW 328i 2007-2008 BMW 328Xi 2007-2008 BMW 330i 2004-2007 BMW 330Xi 2004-2006 BMW 335i 2007-2008 BMW 335Xi 2007-2008 VOLVO S80 2007-2016 VOLVO V70 2008-2010 VOLVO XC70 2008-2016

Est. Labor	Hours		
Gross Weight	0.40	Width	4.75
Net Weight	0.40	Height	2.00
DIM Weight	0.43	Depth	6.25

Kelvin (ColorTemperature) N/A Universal or Vehicle Specific Vehicle Specific

Made In CN Warranty 1 year Lumens N/A Beam Pattern N/A

Prop 65 WARNING: This product can expose you to chemicals, which are known to the State of California to cause cancer and birth defects or other reproductive harm. For more information go to www.P65Warnings.ca.gov

www.racesportinc.com